

SPECS BY LOCATION/TRADE

9/6/2011

Work Write-up/Re-Bid: _____
 Walk-Through Date: _____
 Bid Date: _____
 Initial: _____

Case Number: 07/09-154
 Construction Specialist: Waldemar Orellana
 Phone: 822-1250

Address: 1105 State Street **Unit: Addendum**

Location: 1 - Exterior Approx. Wall SF: 0 Ceiling/Floor SF: 0

| Spec # | Spec | Quantity | Units | Unit Price | Total Price |
|--------|------|----------|-------|------------|-------------|
|--------|------|----------|-------|------------|-------------|

Trade: 10 **Carpentry**

| | | | | | |
|------|---|------|----|-------|-------|
| 3585 | TREAD --EXTERIOR Secure loose step (second tread) and board at front entrance wood landing with screw shank nails. | 1.00 | EA | _____ | _____ |
|------|---|------|----|-------|-------|

Bidder: _____ **Location Total:** _____

Location: 2 - Hall Approx. Wall SF: 0 Ceiling/Floor SF: 0

| Spec # | Spec | Quantity | Units | Unit Price | Total Price |
|--------|------|----------|-------|------------|-------------|
|--------|------|----------|-------|------------|-------------|

Trade: 18 **Ceramic Tile**

| | | | | | |
|------|---|------|----|-------|-------|
| 5410 | CERAMIC TILE--REPAIR Remove loose tiles. Re install ceramic tile of matching color and size using appropriate adhesive. Regrout entire surface. Repair and secure cementitious board as needed. Living to hallway area | 9.00 | SF | _____ | _____ |
|------|---|------|----|-------|-------|

Bidder: _____ **Location Total:** _____

Location: 3 - Master Bathroom Approx. Wall SF: 0 Ceiling/Floor SF: 0

| Spec # | Spec | Quantity | Units | Unit Price | Total Price |
|--------|------|----------|-------|------------|-------------|
|--------|------|----------|-------|------------|-------------|

Trade: 18 **Ceramic Tile**

| | | | | | |
|------|--|------|----|-------|-------|
| 5410 | CERAMIC TILE--REPAIR Remove loose tiles. Re install ceramic tile of matching color and size using appropriate adhesive. Regrout entire surface. Repair and secure cementitious board as needed. Master bathroom floor, by toilet. Cut and install missing skirting tile (floor to wall by base cabinet left side) | 5.00 | SF | _____ | _____ |
|------|--|------|----|-------|-------|

Bidder: _____ **Location Total:** _____

Unit Total for 1105 State Street, Unit Addendum: _____

Address Grand Total for 1105 State Street: _____