

SPECS BY LOCATION/TRADE

9/6/2011

Work Write-up/Re-Bid: _____
 Walk-Through Date: _____
 Bid Date: _____
 Initial: _____

Case Number: _____
 Construction Specialist: Waldemar Orellana
 Phone: 822-1250

Address: 1018 10 Street **Unit: Addendum**

Location: 1 - Bedroom Center Left Approx. Wall SF: 0 Ceiling/Floor SF: 0

Spec #	Spec	Quantity	Units	Unit Price	Total Price
--------	------	----------	-------	------------	-------------

Trade: 10 **Carpentry**

2795	WINDOW REPAIR Repair window to operate correctly. Includes new screens, latches, clips, caulking, and mechanism where missing or broken.	1.00	EA	_____	_____
------	--	------	----	-------	-------

Bidder: _____ **Location Total:** _____

Unit Total for 1018 10 Street, Unit Addendum: _____

Address Grand Total for 1018 10 Street: _____